COMMUNITY WILDFIRE PROTECTION PLAN

APPENDIX-A



GROVE STREET FIRE SAFE COUNCIL, INC.

FOR THE COMMUNITIES LOCATED ALONG THE GROVE STREET
CORRIDOR IN THE WEST SONOMA HILLS

Development

This Community Wildfire Protection Plan (CWPP) was developed by the *Grove Street Fire Safe Council (GSFSC)* with guidance and support from Fire Safe Sonoma, the County of Sonoma, The California Fire Safe Council, and the California Department of Forestry and Fire Protection. This CWPP supplements the Sonoma County Community Wildfire Protection Plan. JULY, 2020

Fire Safe Sonoma www.firesafesonoma.org

DISCLAIMER

Any opinions, findings, conclusions, or recommendations expressed in this publication are those of the authors and do not necessarily reflect the view(s) of any governmental agency, organization, corporation or individual with which the authors may be affiliated. This publication is designed to provide accurate and authoritative information in regard to the subject matter covered. This Community Wildfire Prevention Plan (CWPP) is a work in progress. Various changes are anticipated throughout the Plan over the next several years. Readers are urged to consult with their own agencies having jurisdiction regarding the use or implementation of this Plan, as well as their own legal counsel on matters of concern. While the publisher and authors have used their best efforts in preparing this Plan, they make no representations or warranties with respect to the accuracy or completeness of the contents and specifically disclaim any implied warranties of merchantability or fitness for a particular purpose. No warranty may be created or extended by receiving this publication. The advice and strategies contained herein may not be suitable for your specific situation. The publisher, sponsors and authors shall not be liable for any loss of profit or any other damages, including but not limited to, special incidental and/or consequential damages.

This CWPP is not to be construed as indicative of project "activity" as defined under the "Community Guide to the California Environmental Quality Act, Chapter Three, Projects Subject to CEQA."

This CWPP is intended for use as a planning and assessment tool only, utilizing a compilation of community issues/goals and projected fire mitigation strategies and is not to be construed as indicative of project "activity" as defined under the "Community Guide to the California Environmental Quality Act, Chapter Three, Projects Subject to CEQA." Per the Community Guide, Section 3.1.1, "CEQA only applies to public agency decisions to approve, or actions to carry out, a discretionary project." Any actual project activities meeting this definition of project activity and undertaken by the CWPP participants or agencies listed shall meet with local, state and federal environmental compliance requirements.

Table of Contents

DISCLAIMER	1
GROVE STREET CWPP BASE MAP	3
BASE MAP RISK ASSESSMENT	3
Base Map Risk Assessment Results	4
GROVE STREET CWPP COMMUNITIES AT RISK	5
DIAMOND 'A' RISK ASSESSMENT	5
Diamond 'A' Risk Assessment Results	
GEORGE RANCH RISK ASSESSMENT	
George Ranch Risk Assessment Results	8
LOWER GROVE STREET RISK ASSESSMENT	
Lower Grove Street Risk Assessment Results	
GROVE STREET CWPP ASSETS AT RISK	11
DIAMOND 'A' MUTUAL WATER COMPANY	11
Diamond 'A' Mutual Water Company Risk Assessment Results	12
DIAMOND 'A' RECREATION ASSOCIATION FACILITY	13
Diamond 'A' Recreation Association Facilities Risk Assessment Results	14
GEORGE RANCH COMMUNITY ASSOCIATION CLUBHOUSE RISK ASSESSMENT	
George Ranch Community Association Clubhouse Risk Assessment Results	
GEORGE RANCH MUTUAL WATER COMPANY RISK ASSESSMENT	
George Ranch Mutual Water Company Risk Assessment Results	
GROVE STREET CORRIDOR RISK ASSESSMENT	
Grove Street Corridor Risk Assessment Results	
LYON RANCH RISK ASSESSMENT	
Lyon Ranch Risk Assessment Results	
WESTERBEKE CONFERENCE CENTER RISK ASSESSMENT	
Westerbeke Conference Risk Assessment Results	
COMMUNITY SURVEY	25
GENERAL CONCERNS:	
Specific comments, concerns or ideas	
Summary Chart	
CRITICAL INFRASTRUCTURE:	
Specific comments, concerns or ideas	
Summary Chart	
ASSETS AT RISK	
Specific comments, concerns or ideas	
Summary Chart	
NEIGHBORING AREAS	
Specific comments, concerns or ideas	
Summary ChartFIRE-PRONE INVASIVE SPECIES	
Specific comments, concerns or ideas	
Summary Chart	
Julilliui y Cliui (

RATING

GROVE STREET CWPP BASE MAP

BASE MAP RISK ASSESSMENT

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GS-FSC CWPP BASE MAP

FACTORS

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	High
Thick brush and trees	High
Unmaintained Powerline Corridors	Moderate
High fuel loads	High
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score 106

Low Hazard <41

Moderate Hazard 41-60

High Hazard 61-75

Very High Hazard 76+

HAZARD ASSESSMENT ACCESS Ingress/Egress Inadequate Width of Primary Road Inadequate 5 Passibility Inadequate 5 5 Secondary Road Terminus Inadequate 3 Primary Slope Moderate Street Signs Adequate 1 5 Address Signage Inadequate Roadside Vegetation Inadequate 5 5 Narrow Secondary Inadequate Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges 3 3 Wooden Bridges Moderate Inadequate 5 Gates BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Adequate 1 Siding Materials Inadequate 3 Inadequate Unenclosed Features 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space 3 Moderate FIRE PROTECTION 5 Water Source Moderate Fire Protection 3 Adequate FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Very Steep 10 Slope Moderate 3 Aspect Fuels 5 Extreme Fire Behavior Extreme 10

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Base Map Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Inadequate
Roadside vegetation	Fuels Management, education, funding	Inadequate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Inadequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Adequate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Inadequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Moderate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	
Wood Bridges	Evacuation Planning, modification	Moderate
Water and Fuels		
Water Sources	Develop further sources.	Moderate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	Extreme
Fuels Density (fuels modification)	Planning, funding, education, outreach	Extreme
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Inadequate
Primary Road Slope	Evacuation Planning	Moderate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior		
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Very Steep
Predominant Aspect	Education, outreach, planning	Moderate

GROVE STREET CWPP COMMUNITIES AT RISK

DIAMOND 'A' RISK ASSESSMENT

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GS FSC CWPP DIAMOND A

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	Low
Camping Activities	No
High Level of visitors/activities	No
Understory receptive to ignition	Moderate
Thick brush and trees	Moderate
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	Inadequate	5
Width of Primary Road	Moderate	3
Passibility	Inadequate	5
Secondary Road Terminus	Inadequate	5
Primary Slope	Moderate	3
Street Signs	Adequate	1
Address Signage	Inadequate	5
Roadside Vegetation	Moderate	3
Narrow Secondary	Inadequate	5
Secondary Paved	Adequate	1
Secondary Road Slope	Moderate	3
Unrated Bridges		3
Wooden Bridges	Adequate	0
Gates	Moderate	3
BUILT ENVIRONMENT		
2007 Standards	Inadequate	5
Roofing Materials	Moderate	5
Siding Materials	Inadequate	3
Unenclosed Features	Inadequate	5
UTILITIES		
Utility Ignition Risk	Moderate	3
Lot Size	Moderate	3
Defensible Space	Inadequate	5
FIRE PROTECTION		
Water Source	Adequate	2
Fire Protection	Adequate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	Moderate	3
Slope	Steep	7
Aspect	Moderate	3
Fuels	High	3
Fire Behavior	High	7

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Diamond 'A' Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Moderate
Roadside vegetation	Fuels Management, education, funding	Moderate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Inadequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Moderate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Inadequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Inadequate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels	<u>.</u>	
Water Sources	Develop further sources.	Adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
	, , , , , , , , , , , , , , , , , , , ,	
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS	magation strategies include:	
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Moderate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities	Lideadion Fidining	Auequate
	Education automatic and in the control of the contr	M 3
Underground	Education, outreach, report issues	Moderate
Fire Behavior	Education automated to	Moderate
Fire Hazard Severity Zones	Education, outreach, planning	Steep
Slope	Education, outreach, planning	Moderate
Predominant Aspect	Education, outreach, planning	Moderate

GEORGE RANCH RISK ASSESSMENT

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GS-FSC CWPP GEORGE RANC

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	Moderate
Thick brush and trees	Choose
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

81

Summary Ratingl

Summary Rating / Score

HAZARD ASSESSMENT ACCESS Ingress/Egress Inadequate 5 Width of Primary Road Moderate 3 Passibility Inadequate 5 Secondary Road Terminus Inadequate 5 Primary Slope Moderate 3 Street Signs Adequate 1 Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Siding Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Unity Ignition Risk Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE PROTECTION Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fire Behavior High 7			
ACCESS Ingress/Egress Inadequate 5 Width of Primary Road Moderate 3 Passibility Inadequate 5 Secondary Road Terminus Inadequate 5 Primary Slope Moderate 3 Street Signs Adequate 1 Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Siding Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Figels High 3		RATING	
Ingress/Egress Inadequate 5 Width of Primary Road Moderate 3 Passibility Inadequate 5 Secondary Road Terminus Inadequate 5 Primary Slope Moderate 3 Street Signs Adequate 1 Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Untility Ignition Risk Moderate 3 Defensible Space Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 Fire Protection Adequate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3			
Width of Primary Road Passibility Inadequate Secondary Road Terminus Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate Secondary Paved Secondary Paved Adequate Inadequate Secondary Road Slope Moderate Secondary Road Slope Moderate Secondary Road Slope Moderate Secondary Road Slope Moderate Secondary Road Slope Moderate Secondary Road Slope Moderate Secondary Road Slope Moderate Inadequate Unrated Bridges Adequate Gates Moderate Siding Materials Inadequate Siding Materials Inadequate Siding Materials Inadequate Unenclosed Features Inadequate Utility Ignition Risk Lot Size Moderate Tire Protection Water Source Adequate Fire Protection Adequate Slope Slight Aspect Moderate Slight Aspect Moderate Slight Aspect Moderate Sight Aspect Moderate Sight Aspect Moderate Sight Aspect Moderate Slight Aspect Moderate Sight Aspect Moderate Slight Aspect Moderate Slight Aspect Moderate Slight Aspect Moderate Slight Aspect Moderate Slight Adequate Slight Slight Adequate Slight Slight Sl	ACCESS		
Passibility Inadequate 5 Secondary Road Terminus Inadequate 5 Primary Slope Moderate 3 Street Signs Adequate 1 Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Ingress/Egress	Inadequate	5
Secondary Road Terminus Primary Slope Moderate 3 Street Signs Adequate 1 Address Signage Adequate Roadside Vegetation Moderate Secondary Inadequate Secondary Paved Adequate 1 Secondary Road Slope Unrated Bridges Adequate Wooden Bridges Adequate Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Roofing Materials Siding Materials Inadequate Siding Materials Unenclosed Features Utility Ignition Risk Lot Size Moderate Total Moderate The PROTECTION Water Source Adequate Adequate Fire Protection Adequate Slope Slight Aspect Moderate 3 Firels High 3 High 3	Width of Primary Road	Moderate	3
Primary Slope Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate Secondary Inadequate Secondary Paved Secondary Paved Adequate Unrated Bridges Adequate Unrated Bridges Adequate Gates BUILT ENVIRONMENT 2007 Standards Roofing Materials Siding Materials Siding Materials Unenclosed Features Utility Ignition Risk Lot Size Moderate The PROTECTION Water Source Adequate Adequate Fire Protection Fire Hazard Safety Zone Slight Adequate S Slope Slight Aspect Moderate Adequate Adequat	Passibility	Inadequate	5
Street Signs Adequate 1 Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Siding Materials Moderate 5 Siding Materials Inadequate 5 Utility Ignition Risk Inadequate 5 Utility Ignition Risk Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION 4 Water Source Adequate 3 FIRE BEHAVIOR 5 Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Secondary Road Terminus	Inadequate	5
Address Signage Adequate 1 Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT	Primary Slope	Moderate	3
Roadside Vegetation Moderate 3 Narrow Secondary Inadequate 5 Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Street Signs	Adequate	1
Narrow Secondary Secondary Paved Adequate Secondary Road Slope Moderate Unrated Bridges Adequate Wooden Bridges Adequate Gates Moderate Secondary Road Slope Unrated Bridges Adequate Moderate BUILT ENVIRONMENT 2007 Standards Roofing Materials Siding Materials Siding Materials Inadequate Summer Su	Address Signage	Adequate	1
Secondary Paved Adequate 1 Secondary Road Slope Moderate 3 Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Roadside Vegetation	Moderate	3
Secondary Road Slope Moderate 3 Unrated Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Narrow Secondary	Inadequate	5
Unrated Bridges Adequate 1 Wooden Bridges Adequate 0 Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 3 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Secondary Paved	Adequate	1
Wooden Bridges Adequate Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 3 Unenclosed Features Inadequate 5 Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Secondary Road Slope	Moderate	3
Gates Moderate 3 BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 5 Unenclosed Features Inadequate 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Unrated Bridges	Adequate	1
BUILT ENVIRONMENT 2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 3 Unenclosed Features Inadequate 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Wooden Bridges	Adequate	0
2007 Standards Inadequate 5 Roofing Materials Moderate 5 Siding Materials Inadequate 3 Unenclosed Features Inadequate 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Gates	Moderate	3
Roofing Materials Siding Materials Unenclosed Features Unenclosed Features Utility Ignition Risk Lot Size Moderate 3 Defensible Space Moderate FIRE PROTECTION Water Source Fire Protection Adequate Fire Hazard Safety Zone Slope Slight Aspect Moderate 3 High 3	BUILT ENVIRONMENT		
Siding Materials Inadequate 3 Unenclosed Features Inadequate 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	2007 Standards	Inadequate	5
Unenclosed Features Inadequate 5 UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Roofing Materials	Moderate	5
UTILITIES Utility Ignition Risk Moderate 3 Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Siding Materials	Inadequate	3
Utility Ignition Risk Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Slope Slight Aspect Moderate 3 Fuels High 3	Unenclosed Features	Inadequate	5
Lot Size Moderate 3 Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	UTILITIES		
Defensible Space Moderate 3 FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Utility Ignition Risk	Moderate	3
FIRE PROTECTION Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Lot Size	Moderate	3
Water Source Adequate 2 Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Defensible Space	Moderate	3
Fire Protection Adequate 3 FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	FIRE PROTECTION		
FIRE BEHAVIOR Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Water Source	Adequate	2
Fire Hazard Safety Zone Moderate 3 Slope Slight 4 Aspect Moderate 3 Fuels High 3	Fire Protection	Adequate	3
Slope Slight 4 Aspect Moderate 3 Fuels High 3	FIRE BEHAVIOR		
Aspect Moderate 3 Fuels High 3	Fire Hazard Safety Zone	Moderate	3
Fuels High 3	Slope	Slight	4
	Aspect	Moderate	3
Fire Behavior High 7	Fuels	High	3
	Fire Behavior	High	7

¹ Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

George Ranch Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Moderate
Roadside vegetation	Fuels Management, education, funding	Moderate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Adequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Moderate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Inadequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Moderate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	Adequate
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels		
Water Sources	Develop further sources.	Adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
•		
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS	<u></u>	
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Moderate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior	Lancation, out carry report issues	1.100clate
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
	Education, outreach, planning	Moderate

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GS FSC CWPP LOWER GROVE

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	Low
High Level of visitors/activities	Moderate
Understory receptive to ignition	Low
Thick brush and trees	Moderate
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	Moderate
History of fire ignitions	Low
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

Hazard Category	Score
Low Hazard	<41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	Inadequate	5
Width of Primary Road	Moderate	3
Passibility	Moderate	3
Secondary Road Terminus	Inadequate	5
Primary Slope	Adequate	1
Street Signs	Adequate	1
Address Signage	Adequate	1
Roadside Vegetation	Moderate	3
Narrow Secondary	Inadequate	5
Secondary Paved	Moderate	3
Secondary Road Slope	Adequate	1
Unrated Bridges		0
Wooden Bridges	Adequate	0
Gates	Moderate	3
BUILT ENVIRONMENT		
2007 Standards	Inadequate	5
Roofing Materials	Moderate	5
Siding Materials	Inadequate	3
Unenclosed Features	Adequate	1
UTILITIES		
Utility Ignition Risk	Moderate	3
Lot Size	Adequate	1
Defensible Space	Inadequate	5
FIRE PROTECTION		
Water Source	Moderate	5
Fire Protection	Adequate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	Moderate	3
Slope	Slight	4
Aspect	Moderate	3
Fuels	High	3
Fire Behavior	High	7

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Lower Grove Street Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Moderate
Roadside vegetation	Fuels Management, education, funding	Moderate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Adequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Moderate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Adequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Inadequate
•		-
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels	,	
Water Sources	Develop further sources.	Moderate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
· · · · · · · · · · · · · · · · · · ·	,	
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS	magation ottotegies moude.	
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Adequate
Secondary width	Evacuation Planning Evacuation Planning	Inadequate
Secondary Width Secondary Terminus	_	Inadequate
· · · · · · · · · · · · · · · · · · ·	Evacuation Planning	Adequate
Secondary Slope	Evacuation Planning	_
Secondary Surface	Evacuation Planning	Moderate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior		
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
Predominant Aspect	Education, outreach, planning	Moderate

GROVE STREET CWPP ASSETS AT RISK

DIAMOND 'A' MUTUAL WATER COMPANY

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	Low
Camping Activities	No
High Level of visitors/activities	No
Understory receptive to ignition	Moderate
Thick brush and trees	Moderate
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

, ,	
Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS RATING		
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	inadequate	5
Width of Primary Road	moderate	3
Passibility	inadequate	5
Secondary Road Terminus	inadequate	5
Primary Slope	moderate	3
Street Signs	adequate	1
Address Signage	inadequate	5
Roadside Vegetation	moderate	3
Narrow Secondary	inadequate	5
Secondary Paved	adequate	1
Secondary Road Slope	moderate	3
Unrated Bridges	present	3
Wooden Bridges	none	1
Gates	moderate	3
BUILT ENVIRONMENT		
2007 Standards	none	5
Roofing Materials	moderate	3
Siding Materials	inadequate	5
Unenclosed Features	adequate	1
UTILITIES		
Utility Ignition Risk	moderate	3
Lot Size	small	1
Defensible Space	inadequate	5
FIRE PROTECTION		
	adequate	1
Water Source	-	-
Fire Protection	moderate	3
	moderate	3
Fire Protection	moderate moderate	3
Fire Protection FIRE BEHAVIOR		
Fire Protection FIRE BEHAVIOR Fire Hazard Safety Zone	moderate	3
Fire Protection FIRE BEHAVIOR Fire Hazard Safety Zone Slope	moderate steep	3 5

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Diamond 'A' Mutual Water Company Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	moderate
Roadside vegetation	Fuels Management, education, funding	moderate
Signage		
Street	Education, outreach, funding	adequate
House	Education, outreach, funding	inadequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	moderate
Siding	Education, outreach, retrofit, funding	inadequate
Unenclosed Features	Education, outreach, retrofit, funding	adequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	inadequate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges	, ,	
Unrated Bridges	Evacuation Planning, modification	present
Wood Bridges	Evacuation Planning, modification	none
Water and Fuels		
Water Sources	Develop further sources.	adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	high
Fuels Density (fuels modification)	Planning, funding, education, outreach	high
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	inadequate
Primary Road width	Evacuation Planning	moderate
Primary Road Slope	Evacuation Planning	moderate
Secondary width	Evacuation Planning	inadequate
Secondary Terminus	Evacuation Planning	inadequate
Secondary Slope	Evacuation Planning	moderate
Secondary Surface	Evacuation Planning	adequate
Utilities		
Underground	Education, outreach, report issues	moderate
Fire Behavior		modelato
Fire Hazard Severity Zones	Education, outreach, planning	moderate
Slope	Education, outreach, planning	steep
Predominant Aspect	Education, outreach, planning	moderate

DIAMOND 'A' RECREATION ASSOCIATION FACILITY

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	Low
Camping Activities	No
High Level of visitors/activities	High
Understory receptive to ignition	Low
Thick brush and trees	Low
Unmaintained Powerline Corridors	Moderate
High fuel loads	Low
High Winds	High
History of fire ignitions	Low
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	inadequate	5
Width of Primary Road	moderate	3
Passibility	inadequate	5
Secondary Road Terminus	adequate	1
Primary Slope	moderate	3
Street Signs	adequate	1
Address Signage	inadequate	5
Roadside Vegetation	low	1
Narrow Secondary	adequate	1
Secondary Paved	adequate	1
Secondary Road Slope	adequate	1
Unrated Bridges	moderate	3
Wooden Bridges	none	1
Gates	none	1
BUILT ENVIRONMENT		
2007 Standards	inadequate	5
Roofing Materials	moderate	3
Siding Materials	moderate	3
Unenclosed Features	inadequate	5
UTILITIES		
Utility Ignition Risk	moderate	3
Lot Size	moderate	3
Defensible Space	adequate	1
FIRE PROTECTION		
Water Source	adequate	1
Fire Protection	adequate	1
FIRE BEHAVIOR		
Fire Hazard Safety Zone	moderate	3
Slope	gentle	1
	west facing	1
Aspect		
Aspect Fuels	moderate	3

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Diamond 'A' Recreation Association Facilities Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	none
Roadside vegetation	Fuels Management, education, funding	low
Signage		
Street	Education, outreach, funding	adequate
House	Education, outreach, funding	inadequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	moderate
Siding	Education, outreach, retrofit, funding	moderate
Unenclosed Features	Education, outreach, retrofit, funding	inadequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	adequate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges	_	
Unrated Bridges	Evacuation Planning, modification	moderate
Wood Bridges	Evacuation Planning, modification	none
Water and Fuels	-	
Water Sources	Develop further sources.	adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	moderate
Fuels Density (fuels modification)	Planning, funding, education, outreach	high
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	inadequate
Primary Road width	Evacuation Planning	moderate
Primary Road Slope	Evacuation Planning	moderate
Secondary width	Evacuation Planning	adequate
Secondary Terminus	Evacuation Planning	adequate
Secondary Slope	Evacuation Planning	adequate
Secondary Surface	Evacuation Planning	adequate
Utilities		
Underground	Education, outreach, report issues	moderate
Fire Behavior	Education, outleach, report issues	modelate
Fire Hazard Severity Zones	Education, outreach, planning	moderate
Slope	Education, outreach, planning	gentle
o.opc	Education, outreach, planning	west facing

GEORGE RANCH COMMUNITY ASSOCIATION CLUBHOUSE RISK ASSESSMENT

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GEORGE RANCH COMMUNITY

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	No
Thick brush and trees	Low
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Ratingl

Summary Rating / Score 66

Hazard Category	Score	
Low Hazard	< 41	
Moderate Hazard	41-60	
High Hazard	61-75	
Very High Hazard	76+	

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	Inadequate	5
Width of Primary Road	Moderate	3
Passibility	Moderate	3
Secondary Road Terminus	Inadequate	5
Primary Slope	Moderate	3
Street Signs	Adequate	1
Address Signage	Adequate	1
Roadside Vegetation	Moderate	3
Narrow Secondary	Inadequate	5
Secondary Paved	Adequate	1
Secondary Road Slope	Moderate	3
Unrated Bridges	Adequate	0
Wooden Bridges	Adequate	0
Gates	Adequate	1
BUILT ENVIRONMENT		
2007 Standards	Inadequate	5
Roofing Materials	Adequate	1
Siding Materials	Inadequate	3
Unenclosed Features	Adequate	1
UTILITIES		
Utility Ignition Risk	Moderate	3
Lot Size	Adequate	1
Defensible Space	Moderate	3
FIRE PROTECTION		
Water Source	Adequate	2
Fire Protection	Adequate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	Moderate	3
Slope	Slight	4
Aspect	Moderate	3
Fuels	High	3
1 dels		

¹ Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

George Ranch Community Association Clubhouse Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Adequate
Roadside vegetation	Fuels Management, education, funding	Moderate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Adequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Adequate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Adequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Moderate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	Adequate
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels		
Water Sources	Develop further sources.	Adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Moderate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior	eaction, outlearn, report issues	1110uclate
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
olope	Education, outreach, planning	Moderate

GEORGE RANCH MUTUAL WATER COMPANY RISK ASSESSMENT

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	No
Thick brush and trees	Low
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

Width of Primary Road Moderate Passibility Moderate Secondary Road Terminus Inadequate Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	5 3 3 5 3 1 1
Ingress/Egress Inadequate Width of Primary Road Moderate Passibility Moderate Secondary Road Terminus Inadequate Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	3 5 3 1 1
Width of Primary Road Moderate Passibility Moderate Secondary Road Terminus Inadequate Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	3 5 3 1 1
Passibility Moderate Secondary Road Terminus Inadequate Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	3 5 3 1 1
Secondary Road Terminus Inadequate Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	5 3 1 1 3
Primary Slope Moderate Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	3 1 1 3
Street Signs Adequate Address Signage Adequate Roadside Vegetation Moderate	1 1 3
Address Signage Adequate Roadside Vegetation Moderate	1
Roadside Vegetation Moderate	3
	_
	_
Narrow Secondary Inadequate	5
Secondary Paved Adequate	1
Secondary Road Slope Moderate	3
Unrated Bridges Adequate	0
Wooden Bridges Adequate	0
Gates Adequate	1
BUILT ENVIRONMENT	
2007 Standards Adequate	1
Roofing Materials Adequate	1
Siding Materials Inadequate	3
Unenclosed Features Adequate	1
UTILITIES	
Utility Ignition Risk Adequate	1
Lot Size Inadequate	5
Defensible Space Moderate	3
FIRE PROTECTION	
Water Source Adequate	1
Fire Protection Adequate	3
FIRE BEHAVIOR	
Fire Hazard Safety Zone Moderate	3
Slope Slight	4
Aspect Moderate	3
Fuels High	3
Fire Behavior High	7

¹ Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

George Ranch Mutual Water Company Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Adequate
Roadside vegetation	Fuels Management, education, funding	Moderate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Adequate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Adequate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Adequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Moderate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	Adequate
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels		_ · _
Water Sources	Develop further sources.	Adequate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Moderate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Adequate
Fire Behavior	, , , , , , , , , , , , , , , , , , , ,	
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
Predominant Aspect	Education, outreach, planning	Moderate

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR GROVE STREET CORRIDOROF

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	No
Thick brush and trees	Low
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Rating1

Summary Rating / Score

, ,	
Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	Inadequate	5
Width of Primary Road	Moderate	3
Passibility	Moderate	3
Secondary Road Terminus	Inadequate	5
Primary Slope	Adequate	1
Street Signs	Adequate	1
Address Signage	Moderate	3
Roadside Vegetation	Inadequate	5
Narrow Secondary	Inadequate	5
Secondary Paved	Adequate	1
Secondary Road Slope	Moderate	3
Unrated Bridges	Adequate	0
Wooden Bridges	Adequate	0
Gates	Adequate	0
BUILT ENVIRONMENT		
2007 Standards	Adequate	1
Roofing Materials	Adequate	1
Siding Materials	Adequate	1
Unenclosed Features	Adequate	1
UTILITIES		
Utility Ignition Risk	Moderate	3
Lot Size	Inadequate	5
Defensible Space	Inadequate	5
FIRE PROTECTION		
Water Source	Moderate	5
Fire Protection	Adequate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	Moderate	3
Slope	Slight	4
Aspect	Moderate	3
Fuels	High	3
Fire Behavior	High	7

¹ Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Grove Street Corridor Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Adequate
Roadside vegetation	Fuels Management, education, funding	Inadequate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Moderate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Adequate
Siding	Education, outreach, retrofit, funding	Adequate
Unenclosed Features	Education, outreach, retrofit, funding	Adequate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Inadequate
	,	
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	Adequate
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels		
Water Sources	Develop further sources.	Moderate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Adequate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior		
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
Predominant Aspect	Education, outreach, planning	Moderate

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Moderate
Understory receptive to ignition	High
Thick brush and trees	High
Unmaintained Powerline Corridors	High
High fuel loads	High
High Winds	High
History of fire ignitions	No
Add other risk factor	Choose

Final Scores

Summary Ratingl

Summary Rating / Score

, ,	
Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT	Turne, o	
ACCESS		
Ingress/Egress	inadequate	5
Width of Primary Road	moderate	3
Passibility	inadequate	5
Secondary Road Terminus	inadequate	5
Primary Slope	moderate	3
Street Signs	adequate	1
Address Signage	inadequate	5
Roadside Vegetation	inadequate	5
Narrow Secondary	inadequate	5
Secondary Paved	adequate	1
Secondary Road Slope	adequate	1
Unrated Bridges	none	1
Wooden Bridges	none	1
Gates	adequate	1
BUILT ENVIRONMENT		
2007 Standards	inadequate	5
Roofing Materials	inadequate	5
Siding Materials	inadequate	5
Unenclosed Features	inadequate	5
UTILITIES		
Utility Ignition Risk	high	5
Lot Size	large	5
Defensible Space	inadequate	5
FIRE PROTECTION		
Water Source	inadequate	5
Fire Protection	moderate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	moderate	3
Slope	moderate	3
Aspect	high risk	5
Fuels	high	5
Fire Behavior	high	5

¹ Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Lyon Ranch Risk Assessment Results

Mitigation Strategies Include:	
Evacuation Planning, install "Knox Keys"	adequate
Fuels Management, education, funding	inadequate
Education, outreach, funding	adequate
Education, outreach, funding	inadequate
Education, outreach, retrofit, funding	inadequate
Education, outreach, retrofit, funding	inadequate
Education, outreach, retrofit, funding	inadequate
Education, outreach, funding, inspections	inadequate
Mitigation Strategies Include:	
Evacuation Planning, modification	none
	none
3,	
Develop further sources.	inadequate
Planning, funding, education, outreach	high
	high
, ,	
Mitigation Strategies Include:	
The second strategies metade.	
Evacuation Planning	inadequate
	moderate
	moderate
	inadequate
_	inadequate
	adequate
	adequate
Education outreach report issues	high
Lucation, outreach, report issues	nign
Education outreach planning	moderate
Luucation, outreach, planning	1110001010
Education, outreach, planning	moderate
	Evacuation Planning, install "Knox Keys" Fuels Management, education, funding Education, outreach, funding Education, outreach, funding Education, outreach, retrofit, funding Education, outreach, retrofit, funding Education, outreach, retrofit, funding

IGNITION RISK AND HAZARD ASSESSMENT OVERVIEW FOR WESTERBEKE CONFERENCE

FACTORS	RATING
IGNITION RISK ASSESSMENT	
CONTRIBUTING RISK FACTORS	
History of Lightning	No
Camping Activities	No
High Level of visitors/activities	Low
Understory receptive to ignition	No
Thick brush and trees	Low
Unmaintained Powerline Corridors	Low
High fuel loads	Moderate
High Winds	High
History of fire ignitions	Moderate
Add other risk factor	Choose

Final Scores

Summary Ratingl

Summary Rating / Score

, ,	
Hazard Category	Score
Low Hazard	< 41
Moderate Hazard	41-60
High Hazard	61-75
Very High Hazard	76+

FACTORS	RATING	
HAZARD ASSESSMENT		
ACCESS		
Ingress/Egress	Inadequate	5
Width of Primary Road	Moderate	3
Passibility	Moderate	3
Secondary Road Terminus	Inadequate	5
Primary Slope	Adequate	1
Street Signs	Adequate	1
Address Signage	Moderate	3
Roadside Vegetation	Inadequate	5
Narrow Secondary	Inadequate	5
Secondary Paved	Adequate	1
Secondary Road Slope	Moderate	3
Unrated Bridges	Adequate	0
Wooden Bridges	Adequate	0
Gates	Moderate	3
BUILT ENVIRONMENT		
2007 Standards	Inadequate	5
Roofing Materials	Inadequate	8
Siding Materials	Inadequate	3
Unenclosed Features	Moderate	3
UTILITIES		
Utility Ignition Risk	Moderate	3
Lot Size	Moderate	3
Defensible Space	Moderate	3
FIRE PROTECTION		
Water Source	Moderate	5
Fire Protection	Adequate	3
FIRE BEHAVIOR		
Fire Hazard Safety Zone	Moderate	3
Slope	Slight	4
Aspect	Moderate	3
Fuels	High	3
Fire Behavior	High	7

Summary rating for Ignition Risk Assessment is a judgment call determined by planning committee.

Westerbeke Conference Risk Assessment Results

Risks that can probably be modified	Mitigation Strategies Include:	
Access		
Gates	Evacuation Planning, install "Knox Keys"	Moderate
Roadside vegetation	Fuels Management, education, funding	Inadequate
Signage		
Street	Education, outreach, funding	Adequate
House	Education, outreach, funding	Moderate
Home Hardening/Construction		
Roofing	Education, outreach, retrofit, funding	Inadequate
Siding	Education, outreach, retrofit, funding	Inadequate
Unenclosed Features	Education, outreach, retrofit, funding	Moderate
Defensible Space		
Defensible Space	Education, outreach, funding, inspections	Moderate
Risks that possibly can be modified	Mitigation Strategies Include:	
Access: Bridges		
Unrated Bridges	Evacuation Planning, modification	Adequate
Wood Bridges	Evacuation Planning, modification	Adequate
Water and Fuels		
Water Sources	Develop further sources.	Moderate
Fire Behavior (stragegic fuel breaks)	Planning, funding, education, outreach	High
Fuels Density (fuels modification)	Planning, funding, education, outreach	High
Risks that cannot likely be modified	Mitigation Strategies Include:	
ACCESS		
Primary Roads out	Evacuation Planning	Inadequate
Primary Road width	Evacuation Planning	Moderate
Primary Road Slope	Evacuation Planning	Adequate
Secondary width	Evacuation Planning	Inadequate
Secondary Terminus	Evacuation Planning	Inadequate
Secondary Slope	Evacuation Planning	Moderate
Secondary Surface	Evacuation Planning	Adequate
Utilities		
Underground	Education, outreach, report issues	Moderate
Fire Behavior		
Fire Hazard Severity Zones	Education, outreach, planning	Moderate
Slope	Education, outreach, planning	Slight
Predominant Aspect	Education, outreach, planning	Moderate

COMMUNITY SURVEY


The following is a summary of a community survey conducted by 45 of the residents within the community base-map. The comments, concerns or ideas sections are prioritized with the topmost receiving the most comments of a similar nature.

GENERAL CONCERNS:

Specific comments, concerns or ideas

- Community fund for homeowners that might need help with DF.
- Education about the water system during PSPS
- Public Safety Power Shutdown (PSPS) education
- Vacation rental tenant's education
- Sheltering/evacuating information
- Grove street roadside fuels
- Powerline clearance

Summary Chart



CRITICAL INFRASTRUCTURE:

Specific comments, concerns or ideas

- Water systems
- Escape routes & evacuation
- Power lines & poles.
- Grove street egress & roadside fuels
- Wildlife entrapment

Summary Chart


	frastructure in your community th	•	5. 11 00, piodoo	
intrastructure and	d why you perceive a risk in the co	omment box.		_
Answer	0%	100%	Number of Response(s)	Response Ratio
Yes			20	44.4 %
No			8	17.7 %
Don't know			16	35.5 %
No Response(s)			1	2.2 %
		Totals	45	100%

ASSETS AT RISK

Specific comments, concerns or ideas

- Diamond 'A' Recreation Center
- Wildlife
- Lyon Ranch
- Water systems

Summary Chart




NEIGHBORING AREAS

Specific comments, concerns or ideas

- Valley areas below the community
- Areas between George Ranch and Diamond 'A' Ranch
- Classic Oak savannah open spaces North of the community (some of which ignited in the fires of 2017)
- Surrounding Diamond 'A' there are wooded areas of open space

Summary Chart



FIRE-PRONE INVASIVE SPECIES

Specific comments, concerns or ideas

- High dry grass
- Scotch Broom
- Eucalyptus
- Pampas grass, coyote bush
- Bull Pines

Summary Chart

COMMUNITY WILDFIRE PROTECTION PLAN



GROVE STREET FIRE SAFE COUNCIL, INC.

FOR THE COMMUNITIES LOCATED ALONG THE GROVE STREET CORRIDOR IN THE WEST SONOMA HILLS

Development

This Community Wildfire Protection Plan (CWPP) was developed by the *Grove Street Fire Safe Council (GSFSC)* with guidance and support from Fire Safe Sonoma, the County of Sonoma, The California Fire Safe Council, and the California Department of Forestry and Fire Protection. This CWPP supplements the Sonoma County Community Wildfire Protection Plan. JULY, 2020

Grove Street Fire Safe Council Inc. http://grovestreetfsc.org/

DISCLAIMER

Any opinions, findings, conclusions, or recommendations expressed in this publication are those of the authors and do not necessarily reflect the view(s) of any governmental agency, organization, corporation or individual with which the authors may be affiliated.

This publication is designed to provide accurate and authoritative information in regard to the subject matter covered. This Community Wildfire Prevention Plan (CWPP) is a work in progress. Various changes are anticipated throughout the Plan over the next several years.

Readers are urged to consult with their own agencies having jurisdiction regarding the use or implementation of this Plan, as well as their own legal counsel on matters of concern.

While the publisher and authors have used their best efforts in preparing this Plan, they make no representations or warranties with respect to the accuracy or completeness of the contents and specifically disclaim any implied warranties of merchantability or fitness for a particular purpose. No warranty may be created or extended by receiving this publication. The advice and strategies contained herein may not be suitable for your specific situation. The publisher, sponsors and authors shall not be liable for any loss of profit or any other damages, including but not limited to, special incidental and/or consequential damages.

This CWPP is intended for use as a planning and assessment tool only, utilizing a compilation of community issues/goals and projected fire mitigation strategies and is not to be construed as indicative of project "activity" as defined under the "Community Guide to the California Environmental Quality Act, Chapter Three, Projects Subject to CEQA." Per the Community Guide, Section 3.1.1, "CEQA only applies to public agency decisions to approve, or actions to carry out, a discretionary project." Any actual project activities meeting this definition of project activity and undertaken by the CWPP participants or agencies listed shall meet with local, state and federal environmental compliance requirements.

AMMENDMENTS (as applicable)

Community Wildfire Protection Plan Amendment For The Grove Street Fire Sefe Council

	The Grove Street Fire Safe Council
Date amendment submitted:	
Section(s) amended	
Amended by	

- 1. Provide text of amendment and place in document here using the following format: Use red text and strikeout for text omitted and red text with underline for new text.
- 2. Then remove original pages and replace with amended pages.

Table of Contents

DISCLAIMER	1
INTRODUCTION	4
PRIORITY RATINGS	4
PROJECT CATEGORIES	
Projects have been categorized as follows:	4
PROJECT: DEVELOP AND PUBLISH A COMMUNITY WILDFIRE PREPAREDNESS PLAN	5
PROJECT: GROVE STREET VEGETATION MANAGEMENT	6
PROJECT: EVACUATION EDUCATION	7
PROJECT: COMMUNITY CHIPPING PROGRAM	8
PROJECT: POWER LINE IGNITION TREE REMOVAL	9
PROJECT: HOME ASSESSMENT PROGRAM	10
PROJECT: DEFENSIBLE SPACE EDUCATION	11
PROJECT: DEVELOPMENT OF EVACUATION PROCEDURES AND PROTOCOLS	12
PROJECT: STRUCTURAL RESILIENCE EDUCATION	13
PROJECT: INSTALL AND MAINTAIN FIRE DANGER SIGN	14
PROJECT: WILDLAND FIRE BEHAVIOR EDUCATION	
PROJECT: FIRE METEOROLOGY EDUCATION	16
SOURCES OF FUNDING AND REFERENCE FOR POTENTIAL PROJECTS	17
USDA NATURAL RESOURCE CONSERVATION SERVICE (NRCS)	17
CAL FIRE	
THE CALIFORNIA FIRE SAFE COUNCIL (CFSC) WILDFIRE PREVENTION GRANTS	

INTRODUCTION

In collaboration with community members, local, county, state and federal government agencies, and local and state fire officials, this CWPP establishes and prioritizes wildfire risk reduction projects that have been developed to address the most significant risks identified in the Grove Street Community Risk Assessment. This project list is a living document and will be periodically updated in the future to reflect progress and changing priorities.

PRIORITY RATINGS

- H = High Priority
- M = Medium Priority
- L = Low Priority

PROJECT CATEGORIES

Projects have been categorized as follows:

- Vegetation Management
- Education and Outreach
- Evacuation

Project: Develop and Publish a Community Wildfire Preparedness Plan

Priority: HIGH

Category: Education and Evacuation

Goal: Produce a high-quality booklet available to all residents in the Grove Street Fire Safe Council, Inc. (GSFSCI) area to further their awareness of:

- Preparation and planning
- Evacuation preparedness and procedures
- Preparing to return after a wildfire and have it available on the Grove Street
 Fire Safe Council website

Participants: CAL FIRE, Sonoma Valley Fire Protection District, Department of Emergency Management, Sonoma County Sheriff's Offices, and Fire_Safe Sonoma

Timing: Publish before the 2021 wildfire season and maintained on the GSFSCI website

Potential Cooperating Agencies and/or Programs: George Ranch Community Association, Diamond 'A' Neighborhood Association, Diamond 'A' Recreation Center, Westerbeke Ranch

Potential Funding Sources: Donations for the booklet and possible grants.

Project: Grove Street Vegetation Management

Priority: H

Category: Fuels Reduction, Ignition Reduction, Access & Evacuation

Goal: Reduce/remove hazardous vegetation along primary and secondary roads to support ingress and egress of residents evacuating, emergency vehicles, and reduce wildfire intensity.

- Grove Street is a County maintained road and the only primary access road that serves the communities within the Grove Street Fire Safe Council area.
- Identify critical areas and prioritize. Including:
 - O Trimming overhanging branches, chipping all cut and dead material, removing (cut, pull and/or spray) understory shrubs and pruning
 - O Removal of trees and/or tree branches:
 - Reduce overall fuel levels, particularly lower level fuels (dead and alive) that dramatically increase wildfire intensity (Fuel Reduction)
 - Pose a risk of falling on powerlines (Ignition Reduction)
 - May fall on the road and block access (Access & Evacuation)
- Identify funding and potential resources to implement work
- Include execution plan
- Sonoma County Transportation and Public Works (TPW) has responsibility to keep the
 roadway clear of vegetation within their right of way. This distance should be a
 minimum of 10 feet from the edge of either side of Grove Street. Environmental review
 will be required in the likely case if government funding will be used for this project.

Participants: Licensed tree removal contractors, PG&E, Sonoma County TPW and Department of Emergency Management, Fire Safe Sonoma, and property owners.

Timing: Year-round; avoiding bird nesting season and red flag days

Potential Cooperating Agencies and/or Programs: Cal Fire, Sonoma Valley Fire Protection District

Potential Funding Sources: See the following for potential funding choices and cooperating agencies

Project: Evacuation Education

Priority: H

Category: Education

Goal: To educate and inform residents and property owners regarding approved and authorized evacuation procedures and protocols. To provide residents the knowledge required to make informed decisions, and to evacuate safely, efficiently, and effectively.

- Conduct an ongoing, year-round education/awareness campaign via community workshops and presentations (live and virtual), website information, and newsletters to inform residents of evacuation-related topics.
- Educate residents about the evacuation procedures, protocols, and guidelines developed in conjunction with, and approved by, the Sheriff's Department, Department of Emergency Management, CalFire, and Sonoma Valley Fire District.
- Organize evacuation exercises in collaboration with the Sonoma County Department of Emergency Management.
- Provide educational brochures, checklists, booklets, and other materials for residents to learn about sources of official emergency notifications and wildfire incident updates, evacuation preparedness, procedures, and protocols.

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Sonoma County Department of Emergency Management, PG&E, owners of adjoining properties.

Timing: Year-round educational workshops, presentations, newsletters, and website maintenance. Evacuation exercises scheduled for spring through fall.

Potential Cooperating Agencies and/or Programs: California Office of Emergency Management, American Red Cross

Project: Community Chipping Program

Priority: H

Category/s: Fuels Reduction

Goal: Reduce/remove hazardous vegetation on residential properties to minimize wildfire intensity.

- Removal of fallen branches, overgrown brush and other vegetation around residential properties that comply with County regulations (13A) and create strong defensible spaces around structures.
- The chipper program will offer service to residents who are working on their wildfire safety clearance and creating their defensible space around their homes.
- The program provides an alternative to burning or hauling fire hazardous brush.
- Ease of vegetation disposal will increase the likelihood of residents removing hazardous vegetation.
- Include execution plan

Participants: Licensed tree contractors, Cal Fire, property owners

Timing: Year-round; avoiding bird nesting season and red flag days

Potential Cooperating Agencies and/or Programs:

Potential Funding Sources: National Fire Plan grant from the Cooperative Fire Program of the U.S. Forest Service, Department of Agriculture, Pacific Southwest Region, through the California Fire Safe Council.

Project: Power Line Ignition Tree Removal

Priority: H

Category: Ignition Reduction, Fuels Reduction

Goal: Reduce/remove hazardous vegetation adjacent to any power lines within the entire Grove Street community area.

- Remove any trees, branches, or vegetation (alive, dead, or dying) that pose a risk of falling on powerlines.
- PG&E has the responsibility to keep the power lines clear of vegetation that poses risk
 of wildfire ignition. In many cases, there have been trees marked for removal (over the
 last 3 years) but PG&E has either lost track of this management or has yet to complete
 the project.
- Include execution plan

Participants: PG&E, licensed contractors, Fire Safe Sonoma, property owners

Timing: Year-round; avoiding nesting season and red flag days

Potential Cooperating Agencies and/or Programs:

Potential Funding Sources: See the following for potential funding choices and cooperating agencies

Project: Home Assessment Program

Priority: H

Category: Education

Goal: To conduct wildfire vulnerability assessments of residents' homes throughout the Council's geographic area. The first objective of the assessments is to inform residents of the features and characteristics of their home that may make it more vulnerable to ignition and damage from wildfire. The second objective is to provide residents with a checklist of specific recommendations, action items, and resources that can reduce their home's vulnerability to wildfire. The overall goal of the assessment program is to teach and encourage residents to take action to control and mitigate wildfire risks to their property.

- This project will use the Wildland Fire Assessment Program (WFAP) created by the National Volunteer Fire Council (NVFC) and the U.S. Forest Service. The WFAP applies an 82-point checklist of factors that can determine a home's vulnerability to wildfire.
- Assessors will complete the training course provided by the NVFC. As practicable, supplemental training will be obtained from NFPA courses and certifications, and the study of professional research, including publications of the Office of the State Fire Marshall (OSFM) and the Insurance Institute for Business & Home Safety (IIBHS).
- Upon completion of the home assessment, the resident will receive a written report of recommendations applicable to their property. All assessments are completely voluntary and free of charge, although residents will be invited to make donations to the GSFSC if they find the assessment to be of value.

Participants: Grove Street Fire Safe Council Board Members, property owners. **Timing:** Year-round home assessments.

Potential Cooperating Agencies and/or Programs: Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Permit Sonoma, PG&E.

Potential Funding Sources: Individual donations, Cal Fire Grants, IIBHS.

Project: Defensible Space Education

Priority: H

Category: Education and Outreach

Goal: To educate and inform residents and property owners regarding the principles of defensible space to minimize structural ignition and damage from wildfire. To create a culture of year-round implementation of defensible space strategies. To provide the knowledge property owners can use to control and mitigate wildfire risks from vegetation adjacent to structures.

- Conduct an ongoing, year-round education/awareness campaign via community workshops and presentations (live and/or virtual), website information, and newsletters to educate residents and property owners about defensible space fuel reduction.
- Conduct educational sessions to show specific examples of defensible space implementation using before-and-after case studies.
- Provide educational brochures, checklists, research articles, and other materials for residents to use as references while implementing defensible space strategies.

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Permit Sonoma, PG&E, property owners, licensed arborists, landscape designers, and landscape contractors.

Timing: Year-round educational workshops, presentations, newsletters, and website maintenance. On-site educational sessions scheduled for spring through early fall. Potential Cooperating Agencies and/or Programs: Sonoma Ecology Center, Sonoma Master Gardeners.

Project: Development of Evacuation Procedures and Protocols

Priority: H

Category: Evacuation

Goal: To develop a comprehensive set of procedures, protocols, and guidelines (the "Evacuation Plan") for the safe, efficient, and orderly evacuation of the Council area in the event of a wildland fire incident. Grove Street Fire Safe Council, Inc. will collaborate with the following agencies and stakeholders to develop the Evacuation Plan:

- Sonoma County Sheriff's Office
- Sonoma County Department of Emergency Management
- Sonoma County Department of Public Works
- Cal Fire
- Sonoma Valley Fire District
- Pacific Gas & Electric
- Adjoining landowners

The objective of the Evacuation Plan is to provide residents with practical evacuation guidelines they should follow before and during a wildfire incident. The Evacuation Plan must be developed in collaboration with the above-listed agencies and stakeholders to obtain their approval and authorization.

It is anticipated that the Evacuation Plan will include, but not be limited to, consideration of the following topics:

- Sources of situational awareness.
- Evacuation alerts and notifications.
- Agency roles and functions regarding evacuations.
- Voluntary evacuation procedures and guidelines.
- Shelter in place guidelines.
- Evacuation routes and protocols for their use.
- Evacuation alternatives (Temporary Refuge Areas, Safety Zones).

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Sonoma County Department of Emergency Management, Sonoma County Sheriff's Office, Sonoma County Department of Public Works, PG&E, adjoining property owners.

Timing: It is anticipated that development of the Evacuation Plan will begin in August 2020, with completion as soon as possible, but no later than October 31, 2020.

Potential Cooperating Agencies and/or Programs: American Red Cross

Project: Structural Resilience Education

Priority: M

Category: Education

Goal: To educate and inform residents and property owners regarding the principles of firewise design and construction to minimize structural ignition and damage from wildfire. To create a culture of year-round implementation of fire-wise design, retrofitting, and construction. To provide residents the knowledge they need to control and mitigate wildfire risks to structures from radiant heat, embers, and direct flame impingement.

- Conduct an ongoing, year-round education/awareness campaign via community
 workshops and presentations (live and virtual), website information, and newsletters to
 educate residents and property owners about the sources of structural ignition and the
 design and construction strategies to mitigate such sources.
- Conduct educational sessions to show specific examples of fire-wise design and construction using before-and-after case studies.
- Provide educational brochures, checklists, research articles, and other materials for residents to use as references while implementing fire-wise design, retrofitting, and construction principles.

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Permit Sonoma, PG&E, property owners, licensed contractors, architects, and engineers.

Timing: Year-round educational workshops, presentations, newsletters, and website maintenance. On-site case studies scheduled for spring through early fall.

Potential Cooperating Agencies and/or Programs: Insurance Institute for Business & Home Safety

Project: Install and Maintain Fire Danger Sign

Priority: MEDIUM

Category/s: Emergency Notification and Communication

Goal: Enhance community awareness of wildfire danger.

- Identify location and install already developed Community Sign as additional form of communication for Red Flag days and other community emergency information
- Develop a protocol for managing sign messaging and maintaining

Participants: Sonoma Valley Fire District, Selected Community Representatives

Timing: April-November, ongoing

Potential Cooperating Agencies and/or Programs: Sonoma Valley Volunteer Firefighters Association, GSFSC Volunteers

Potential Funding Sources: Individual donations, CalFire grants

Project: Wildland Fire Behavior Education

Priority: L

Category: Education

Goal: To educate and inform residents and property owners about the commonly-accepted fundamental scientific principles of wildland fire behavior. The educational topics will provide residents with knowledge they can use to evaluate wildland fire risks based on fire science research, and to dispel commonly-held misconceptions. The purpose is to encourage better understanding of the sources and nature of wildfire risks in the Wildland Urban Intermix and Interface. The objective is to provide knowledge that residents can use to manage and mitigate wildfire risks and to understand evacuation strategies.

- Conduct an ongoing, year-round education/awareness campaign via community workshops and presentations (live and virtual), website information, and newsletters to inform residents and property owners of the fundamentals of wildland fire behavior.
- General topics will include fundamental aspects of fuels, topography, and weather.
- The general principles will be applied to the specific conditions in the Council area.
- Provide educational brochures, research articles, and other materials for residents to
 use as references to understand and evaluate risks and the most effective means of
 mitigating them.

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, Cal Fire, Sonoma Valley Fire District, Permit Sonoma, PG&E, property owners, licensed contractors, architects, and engineers.

Timing: Year-round educational workshops, presentations, newsletters, and website maintenance. On-site educational sessions scheduled for spring through early fall.

Potential Cooperating Agencies and/or Programs: Insurance Institute for Business & Home Safety (IIBHS)

Project: Fire Meteorology Education

Priority: L

Category: Education

Goal: To educate and inform residents regarding basic meteorological principles relevant to wildfires and how they apply to the Council area. To provide a basic understanding of the large-scale climatological systems that produce Red Flag Warnings so residents may better anticipate them. To provide an understanding of how local meteorological conditions are affected by the large-scale systems and how local fire behavior is affected by local conditions.

- Conduct an ongoing, year-round education/awareness campaign via community
 workshops and presentations (live and virtual), website information, and newsletters to
 educate residents and property owners about fundamental meteorological principles
 applicable to wildfire conditions, prediction, and local effects.
- Provide educational resources, research articles, and other materials to allow residents to understand the causes and nature of fire weather incidents.
- Inform residents of online sources of fire weather conditions, predictions, and data.

Participants: Grove Street Fire Safe Council Board Members, Fire Safe Sonoma, CalFire, PG&E.

Timing: Year-round educational workshops and presentations, newsletters, and website features.

Potential Cooperating Agencies and/or Programs: National Weather Service, San Jose State Fire Weather Research Laboratory.

Sources of Funding and Reference for Potential Projects

Below are available programs for potential funding and reference for planning and/or implementing wildfire prevention and community protection in the Grove Street Fire Safe Council CWPP area:

USDA Natural Resource Conservation Service (NRCS)

This entity provides cost-share funding assistance for forest practice and road related projects through the following program:

The Environmental Quality Incentive Program (EQIP) provides financial and technical assistance to agricultural producers and forest landowners in order to address natural resource concerns and deliver environmental benefits such as improved water and air quality, conserved ground and surface water, reduced soil erosion and sedimentation or improved or created wildlife habitat.

CAL FIRE

CAL FIRE provides cost-share funding assistance for forest stand improvement projects and other vegetation treatments through the following programs:

California Forest Improvement Program (CFIP): The purpose of the CFIP program is to encourage private and public investment in, and improved management of, California forest lands and resources. This focus is to ensure adequate high-quality timber supplies, related employment and other economic benefits, and the protection, maintenance, and enhancement of a productive and stable forest resource system for the benefit of present and future generations.

Vegetation Management Program (VMP): CAL FIRE's VMP is a cost-sharing program that focuses on the use of prescribed fire, and some mechanical means, for addressing wildland fire fuel hazards and other resource management issues on State Responsibility Area (SRA) lands. VMP allows private landowners to enter into a contract with CAL FIRE to use prescribed fire and/or mechanical treatments to accomplish a combination of fire protection and resource management goals. Implementation of VMP projects is by CAL FIRE Units. The projects which fit within a unit's priority areas (e.g., those identified through the Fire Plan) and are considered to be of most value to the unit are those that will be completed. Landowners who choose to apply for participation in the Vegetation Management Program should contact their local Battalion Unit for more details.

CAL FIRE also provides several competitive grant funding programs for vegetation treatments:

California Climate Investments (CCI) grants – Fuels Reduction: CAL FIRE will solicit and competitively award grants that reduce hazardous fuels and are designed to meet greenhouse gas emission objectives. Payments will be made to grantees via

reimbursements. All projects shall be designed to meet greenhouse gas emission objectives. These objectives include increased carbon sequestration in trees retained on the project site, reduction of wildfire hazards to reduce wildfire emissions, utilization of biomass to offset use of fossil fuels, and utilization of solid wood materials to offset emissions resulting from removal of vegetation. Vegetation treatment forestry prescriptions will focus on treating understory trees and brush with a goal of reducing fire hazards, improving tree growth, stabilizing carbon in retained trees, and increasing forest resilience. All projects will include a scientific methodology to calculate and quantify the GHG emission reductions resulting from the project. Priority shall be given to projects which utilize biomass and other solid wood products; provide assurance of achieving and retaining GHG benefits, and projects which are included in a local fire plan or conservation plan; and projects that have a documented assessment of need for providing wildfire protection of human infrastructure and watershed values, while providing other co-benefits (reduced

forest pest damage, air-shed improvements in non-attainment air basins, invasive weed control, improvement to wildlife habitat, etc.)

Forest Health (CCI) Grants: The Forest Health GGRF Grant Program is a new program and will use funds provided by the Greenhouse Gas Reduction Fund for California Climate Investments administered by CAL FIRE. Through the Forest Health CCI Grant Program, CAL FIRE funds and implements projects to proactively restore forest health in order to reduce greenhouse gases, to protect upper watersheds where the state's water supply originates, to promote the long-term storage of carbon in forest trees and soils, minimize the loss of forest carbon from large, intense wildfires, and to further the goals of the California Global Warming Solutions Act of 2006 (Assembly Bill 32, Health and Safety Code Section 38500 et seq.) (AB 32). Forest Health CCI Grant projects must focus on large, landscape-scale forestlands composed of one or more landowners, which may cover multiple jurisdictions. Projects must be comprised of logical management units and greater consideration will be given to organizations with a proven record of success in achieving consensus-based solutions between stakeholder groups with different priorities and perspectives. Forest Health CCI Grant projects may include reforestation, fuel reduction, pest management, conservation, and biomass utilization intended to increase forest health, increase carbon storage in forests, reduce wildfire emissions and protect upper watersheds, where much of the State's water supply originates. Projects that implement a mix of these activities, with multiple partners will be given priority.

The California Fire Safe Council (CFSC) wildfire prevention grants.

Funding from the California Fire Safe Council is provided through master grants to CFSC by the U. S. Forest Service to administer the Grants Clearinghouse program, with CFSC issuing subawards to successful applicants for the following areas of hazard mitigation competitive grants:

Hazardous fuels reduction and maintenance projects on non-federal land

- Community Wildfire Protection Plans (CWPP) and other planning or assessment documents
- Prevention and mitigation education and outreach opportunities for landowners and residents in at-risk communities

COMMUNITY WILDFIRE PROTECTION PLAN



GROVE STREET FIRE SAFE COUNCIL, INC.

FOR THE COMMUNITIES LOCATED ALONG THE GROVE STREET
CORRIDOR IN THE WEST SONOMA HILLS

Development


This Community Wildfire Protection Plan (CWPP) Appendix-B was developed by the *Grove Street Fire Safe Council (GSFSC)* with guidance and support from Fire Safe Sonoma, the County of Sonoma, The California Fire Safe Council, and the California Department of Forestry and Fire Protection. This CWPP supplements the Sonoma County Community Wildfire Protection Plan. JULY, 2020

Contents


Table of Contents

Area Map	
COMMUNITY MAP	
WUI MAP	
FIRE HISTORY MAP	
VEGETATION MAP	
PARCEL MAP	8
FUEL LADDER MAP	9
SLOPE MAP	10
ASPECT MAP	11


Area Map




Community Map




Fire Hazard Map






Fire History Map




Vegetation Map




Parcel Map




Fuel Ladder Map



Slope Map



Aspect Map



COMMUNITY WILDFIRE PROTECTION PLAN



GROVE STREET FIRE SAFE COUNCIL, INC.

FOR THE COMMUNITIES LOCATED ALONG THE GROVE STREET
CORRIDOR IN THE WEST SONOMA HILLS

Development

This Community Wildfire Protection Plan (CWPP) was developed by the *Grove Street Fire Safe Council (GSFSC)* with guidance and support from Fire Safe Sonoma, the County of Sonoma, The California Fire Safe Council, and the California Department of Forestry and Fire Protection. This CWPP supplements the Sonoma County Community Wildfire Protection Plan. JULY, 2020

Grove Street Fire Safe Council Inc. http://grovestreetfsc.org/

Table of Contents

HISTORICAL REFERENCES	
BRIEF HISTORY OF SOUTHERN SONOMA VALLEY AND WESTERN GROVE STREET	
HISTORY OF GEORGE AND ANDERSON RANCHES	
The George Ranch	
The Anderson Ranch (Currently Diamond A Ranch Estates)	
RELEVANT MAPS (FOR OTHER MAPS SEE APPENDIX-C)	8
GEOLOGY OF GSFSC AREA	8
VEGETATION MAP	8
MAP OF TOPOGRAPHY OF GSFSC	9
DIAMOND 'A' COMMUNITY MAP	10
GEORGE RANCH COMMUNITY MAP	10
MAP OF LOWER GROVE STREET COMMUNITY	11

HISTORICAL REFERENCES

Brief History of Southern Sonoma Valley and Western Grove Street

The Coast Miwok lived in the Sonoma and Petaluma Valleys and traversed Sonoma Mountain regularly. They climbed its flanks to harvest Black Oak acorns, one of their staple foods. They searched for obsidian to make arrowheads. They obtained water from the many streams, including Carriger Creek, and the springs on the Mountain. They utilized the 120° warm springs along Carriger Creek around 2140 and 2220 Grove Street. There was an archeological dig near that location where beads, shards and bones were found. The mountain, named Oona-Pa'is by the Coast Miwok, was revered as the center of their world. Unfortunately, a smallpox epidemic among other factors wiped out 90 percent of the area's Native people.

In the early 1800's the Spaniards arrived. The Sonoma Mission known as Mission San Francisco Solano was founded in 1823. Soon the Mexicans wrested control of the area from the Spaniards, and General Vallejo came to the area in 1830 to set up a Mexican military presence as a barrier against Russian expansion south from Fort Ross. General Vallejo was granted 66,000 acres between the Petaluma River and Sonoma Creek including the area where GSFSC is situated. Vallejo ran cattle, sheep and horses on his ranch.

In 1846 American settlers in Sonoma declared California a separate state from Mexico, calling it the Bear Flag Republic. The United States government declared California a territory of the United States within a couple of weeks, but they were still at war with Mexico over certain western territories. By 1848 the United States won the war with Mexico and Sonoma Mountain was officially part of the United States. About that time American settlers began to arrive in Sonoma Valley. The Gold Rush of 1849 added to the flow of settlers. This migration was sped up by the coming of the railroads to Sonoma in 1870's and 1880's. Sonoma Mountain was denuded of trees by 1900, which were used to build San Francisco and fuel development and transportation in the Bay Area. Over the ensuing 100 plus years the hardwoods and conifer forests have returned.

Grove Street was once a private road from El Rancho Rodeo up to the Anderson Ranch, but in order to maintain it as private it had to be closed one day each year. Rumor has it that one-year Bucky Anderson was indisposed and left his post, someone accessed the road and the road became public. Apparently, during Prohibition there was a still down in Carriger Creek by a horse barn opposite 2305 Grove Street. Additionally, there allegedly used to be a rattlesnake gun inside a glass box by the road posted, "In case of Rattlesnake break glass." And finally, there used to be so many steelhead in the Carriger Creek that the best way to fish for them was to take a pitchfork, spear the fish and throw them up on the bank. Those days are long gone, sadly.

Within the area there have been coal mines with attendant narrow gauge railroads up in the Diamond A Ranches. There have been quarries including the one north of Grove Street near the double right angle turns, and one on the George Ranch Community that provided cobblestones for San Francisco streets. There used to be a water company, the Yulupa Mutual Water

Company, that stored water in a large reservoir on what is now the Westerbeke Property and provided the water for El Verano

History of George and Anderson Ranches

The George Ranch

By Danny Kaplan, with a little help from Harold Marsh, Karen Everard and Steve Pease

Originally part of General Vallejo's land grant, the George Ranch entered modern history when in 1942 it was acquired by James P. George. Mr. George had been successful in the Oil and Gas business in Southern California but for the next 40 years lived on this property. He named it the Lazy Bar G and operated it as a cattle ranch. The 1000 acres was 3 miles west of Sonoma Plaza and varied in elevation from 400 to 1600 feet.

In the late 1970's one of a group of Dutch investors, Mr. Nick Sandmann, contacted a boyhood friend, Mr. Pieter Everard, a Sonoma accountant. Pieter apprised him of the George property and after some negotiation Mr. George sold the Lazy Bar G Ranch to Damstraat Investors for \$2.1 million.

Damstraat Investors (named for a street in Amsterdam) then experienced a difficult few years involved in site evaluations, EIR's, and soil, geological and archeological evaluations. Finally, in 1982 the County of Sonoma approved a major subdivision of 56 lots to be developed in four phases. During this time a financial rearrangement had passed the property to Centennial Savings and Loan.

The County endorsed the developer's vision of a low density subdivision with underground utilities, private roads, scenic easements, and agricultural activities. Specifically, several large agricultural lots were delineated for cattle or sheep grazing and vineyards. Home building lots were prepared with scenic easements to preserve views from the valley floor and easements for hiking and equestrian trails. The open and natural concept included a recreational area with a pond and clubhouse.

When marketing began in 1983-84 the George Ranch consisted of 51 residential building lots varying from 3 to 20 acres. Two large properties, each several hundred acres were reserved for agricultural purposes and scenic preservation. Three other lots were reserved for vineyard development. The Georges kept their original farm house and its 15 acres and this parcel was only later incorporated into the George Ranch.

As a California Community Interest Development, the GR is governed by its homeowners through a five-person elected Board of Directors. The Board supervises several committees whose responsibilities include maintenance of common areas, management of the GR

Mutual Water Company and review and approval of building plans. Their mandate is to preserve the rural nature and aesthetic characteristics of the Ranch.

Today all but a few lots have been developed. Some homeowners are retired but many are active in various business and professional careers. The George Ranch is a beautiful and interesting area that has fulfilled the original concept of a low-density subdivision with a rural character, agricultural emphasis, environmental sensitivity and largely secluded homes.

The Anderson Ranch (Currently Diamond A Ranch Estates)

by Beverly Perrin, John Barinaga and Helen Bates, edited by Bruce Hoadley (2012)

The largest subdivision on Sonoma Mountain is known as "Diamond A," a rural residential community accessed via Grove Street on the South East slope of our beautiful mountain. How did these 1,200 acres of paradise transition from Miwok hunting grounds, to a subdivision of 240 parcels, during the past two centuries? Who were the central characters in this history? Was there any public oversight of the subdivision process, or was it driven primarily by private interests? Could it happen again in the 21st century? These are the questions addressed in this brief history.

In 1769, when the Miwok Indians, of the Sonoma Coast, first came in contact with Europeans, they numbered about 1,500. Their hunting grounds included all of Sonoma Mountain. By 1930 the Miwok Indians numbered only about 500. The mountain had been divided into parcels, and passed through various owners. However, the coyotes, who the Miwok Indians believed to be their ancestors and Creator God, still prowl the mountain. They howl near the ridge line at night, ignoring the artificial boundaries that have been placed on the land.

From 1834 to 1857, the southern portion of Sonoma Mountain, from the Petaluma River to Sonoma Creek, was part of "Rancho Petaluma." According to the Petaluma State Historic Park website, Rancho Petaluma was a 44,000-acre land grant to General Mariano Vallejo in 1834. It was later extended to more than 66,000 acres. The Rancho stretched eastward from Petaluma Creek, over the hills, and down to Sonoma Creek, including all the land that lay between those two waterways, from the edge of San Francisco Bay to Glen Ellen. In 1857, Vallejo decided to sell his Petaluma Adobe and some of the land around it. By 1866, when the Rowe survey of the western portion of Rancho Petaluma was recorded, the 66,000 acres had been split into many parcels - some sold by General Vallejo, others taken by Anglo squatters.

The 1897 Illustrated Atlas shows the unmistakable shape of what was to become the Diamond A Ranch, labeled "Henry A. Hardin 1,240 acres". Henry Andrew Hardin was born in Kentucky in

1833. In 1852, he joined an ox-team train, which traveled from Missouri to Sonoma County. He bought and sold various parcels before buying the 1,240 acre Ranch in 1877 from Edward Halloran. Hardin owned this Ranch until his death in 1920. Three of his daughters sold the Ranch to the Felder family in 1934. The Felder family owned the Ranch for a few years, and then sold it to the Berrien Anderson family in 1938.

In 1961, Anderson sold the ranch to the developers, Thomas Burke & Jack Fisher, for \$400,000. Jack Fisher lived at 3775 Burke Place, in Unit #1 of the Diamond A Ranch Estates, until his death on March 12, 2003.

In 1965, the Preliminary Master Plan for the Diamond A Ranch Estates divided 1,220 acres into 482 home sites of 1.5 to 2.5 acres each. The plan included extensive recreation areas along Carriger Creek and on the steep wooded slopes. This Preliminary Master Plan showed Units 1 through 5, much as they were later developed. Of the 482 lots, 290 were not completed as shown. Instead, they were later consolidated into larger lots. T. E. Burke recorded the declarations for Unit 1 on 11/8/1962, and Unit 2 on 8/23/1962. They were recorded in the name of Kenleigh Homes Inc. Unit 1 had 25 lots, and Unit 2 had 28 lots. The original broker for the development was Robert Garlick. According to Robert Garlick's son, Dave, the Plans called for a multiphase development, which would include 500 to 600 lots ranging in size from 1.5 acres to 3 acres. Phase one included excavation and construction of the main road, leading from the old Van Hoosear Ranch, at the base of the Mountain, to the Diamond A entrance. A new road construction method was used. It allowed for a steep but straight approach up the hill. The old one-lane road was not steep, full of turns, and took about 20 minutes to navigate. The first two phases of the project went relatively well. Lots typically sold for \$6,000 to \$8,000. Many Bay Area residents fell in love with the magnificent views and beautiful hillsides. Live Oak, White Oak, and Pepperwood were in abundance. The golden hills turned purple and orange each spring, as lupine and poppies dominated the fields. The exclusive realtor was Bob Garlick, who worked out of the old ranch house.

After awhile, the undeveloped property changed hands. Two Stanford graduates fell in love with the property. They made an offer that Fisher and Burke could not turn down. These two developers were very much into promoting and marketing. San Francisco radio stations encouraged Bay Area residents to visit the Ranch. The visits included a tour in a Rolls Royce Jeep, conducted by "Trail Boss Bob" Garlick. Phase Three was started, and looked promising for the development.

Disaster hit in the late 1960's. The owner of one on the lots, located slightly below the old ranch house, undertook significant grading without permits. With the first winter rain, a landslide from this area caused significant damage to the road below. Red flags went up at the county. A moratorium on future building was put in place, until geologic and landslide studies were completed. This study concluded that 27 lots were high-risk, 65 were low risk, and 95 lots were intermediate risk. As a result, the county tightened foundation requirements. The process took a couple of years. This delay caused the developers to lose the Ranch through foreclosure. During those bleak years, the developers were trying to sell the remaining acres in one block.

One prospective buyer had big plans to develop a world-class golf course. Trail Boss Bob, in his Jeep, took the golf course developer to the highest point on the Ranch, to best view the undeveloped areas. The jeep was parked at the top of the hill. As they got out, the stick shift was accidentally knocked into neutral. Both men watched as the Jeep went down the hill and crashed into an oak tree. The walk out took about two hours. That was the end of the golf course plans. The remaining acres were finally sold to the highest bidder, at the steps of the county courthouse. From that point on, the development of the remaining acres took a different direction. The future phases included much larger lots ranging from 10 to 40 acres.


On February 18,1965, the declaration for Unit 3, with 56 lots, was filed in the name of Fisher and Burke, Inc. by T. E. Burke, President and Jack Fisher, Secretary Treasurer. On October 29, 1965, William J. Troy, President of the Sonoma Land Corporation, filed the declaration for Unit 4, with 4 lots. On December 29, 1966, the Sonoma Development Corporation President, William J Troy, filed the declaration for Unit No 5, with 71 lots. On December 23, 1976, the Piombo Corporation filed a declaration to divide the northeast sector of the Ranch into lots 1 through 16, to be named Diamond A Ranches.

As a result of all these declarations, the old Anderson Ranch evolved into two subdivisions: [1] The Diamond A Ranch Estates, and [2] The Diamond A Ranches. Over time, the leftover pieces were further subdivided and some were built. In a 1999 count, the lots on the old 1,221-acre Ranch were: [1] Diamond A Ranch Estates subdivision with 190 lots (1962-1966), [2] Diamond A Ranches subdivision with 16 lots (1976), and [3] The balance divided into 34 lots. There are a total of 240 lots. This is about half of the 482 lots in the 1965 Preliminary Master Plan. Out of the 240 lots in the 1999 count, 188 had been built, and 52 had not been built. Several lots have been built since 1999. Our 2007 telephone directory lists 199 households. Note, in some cases, there is more than one household per lot.


From this history it seems that there was little planning or oversight by the County until Mother Nature intervened in the form of a landslide. As a result of these interventions, the original developers lost the land, and Sonoma Mountain was spared from a much denser development on its eastern flank. Could a subdivision like Diamond A happen again? Probably not. Sonoma Mountain Preservation helped enact Guidelines for Development in 1998. These guidelines are now closely monitored by Sonoma County and Sonoma Mountain Preservation.

RELEVANT MAPS (For other maps see Appendix-C)


Geology of GSFSC Area




Vegetation Map




Map of Topography of GSFSC



Diamond 'A' Community Map



George Ranch Community Map



Map of Lower Grove Street Community

